



UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY

RECEIVED

DATE ENTERED

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*  
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC            The Old Manse

AND/OR COMMON

The Old Manse

**2 LOCATION**

CITY, TOWN  
Concord

\_\_\_\_ VICINITY OF

COUNTY  
Middlesex

STATE  
Massachusetts

**3 PHOTO REFERENCE**

PHOTO CREDIT Polly M. Rettig, Landmark Review Project    DATE OF PHOTO November 1974

NEGATIVE FILED AT Historic Sites Survey, NPS, 1100 L. Street, N.W., Washington, D.C. 20240

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. 1

view from southeast showing front and side elevations and sheds attached at southwest corner.





UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY

RECEIVED

DATE ENTERED

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*  
TYPE ALL ENTRIES --ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC    The Old Manse

AND/OR COMMON

The Old Manse

**2 LOCATION**

CITY, TOWN  
Concord

\_\_\_\_ VICINITY OF

COUNTY  
Middlesex

STATE  
Massachusetts

**3 PHOTO REFERENCE**

PHOTO CREDIT    Polly M. Rettig, Landmark Review Project    DATE OF PHOTO    November, 1974

NEGATIVE FILED AT    Historic Sites Survey, NPS, 1100 L. Street, N.W, Washington, D.C.    20240

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT. GIVE BUILDING NAME & STREET

PHOTO NO. 2

view from northwest showing side and rear elevations and kitchen ell  
at southwest corner